



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

March 9, 2006

Dr. Roger C. Westman
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 191003-2029
ATTN: James W. Hagedorn

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 06-0088
ACHD Reference Number: 7313
#7 Battery Igniter Flare
USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the outage. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac
Plant Manager
Clairton Works

RECEIVED
MAR 20 2006
Protection Division (3AP12)

NOTICE OF BREAKDOWN OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 06-0088
ACHD Reference Number: 7313
2. Date & Time of Breakdown: Date: 03/08/06 Time: 1415 hours
3. Company Name: U.S. Steel Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: #7 Battery Igniter Flare
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: Due to availability concerns, an additional 30 second flare test was performed on the #7 Battery Igniter Flare.
8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.) Released products of combustion of Coke Oven Gas.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). Eye, Nose and Throat Irritant.
 - C. Amount of each type emitted (or likely to be emitted). Light to Moderate
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The test was completed and the automatic system was available for service.
10. Facility back in operation - Date: 03/08/06 Time: 1417 hours

Signature Coleen M. Davis Date 3/9/06
Coleen M. Davis
Senior Environmental Control Engineer Phone: 233-1015